



Technical Advisory Memo

No: TAMF4-2018-014
Date: June 11, 2018
To: All
Subject: HPD Bulletin F4-2018-EN003 Fuel Pump Bolts

See this HPD bulletin for details regarding replacement of fuel pump bolts that have broken. Fuel leaks have resulted from this breakage.

Replacement with the proper bolts is mandatory. Cars with the faulty bolts, as identified in HPD Bulletin F4-2018-EN003, will not pass tech at events after the date of this bulletin.

Normally, cars presented to tech with missing engine seals would be reported to the Stewards and possibly subject to penalties per the SCCA Sporting Regulations, section 28.5.

However, cars may be presented to tech at the Mid Ohio 2018 F4 event with missing fuel pump seals, provided that the correct bolts, as identified in the HPD bulletin, have been installed. SCCA tech staff will install a temporary SCCA seal, to serve until HPD installs their seal.