

Stewards Decisions - Teams
2021 F4 United States and FR Americas Championships



| Competitor | Car # | Class | Circuit | Session Date | Session | Article # / Offense: | Decision | Rep | Fine | Dec. # |
|---------------------------|-------|-------|--------------------------------|---------------|-----------------|---|--|-----|--------|--------|
| Alliance Racing | 28 | F4 | Michelin Raceway Road Atlanta | 27 March 2021 | Race 2 | 26.3(b) - Fire extinguisher not in armed position for on track session | Team reprimand | 1 | \$ - | 114 |
| Alliance Racing | | | | | | | Total Reprimands and Fines | 1 | \$ - | |
| Crosslink Competition | 9 | FR | Brainerd International Raceway | 17 July 2021 | Qualifying | 26.3(b) - Fire extinguisher not in armed position for on track session | Team reprimand | 1 | \$ - | 429 |
| Crosslink Competition | 9 | FR | Road America | 17 May 2021 | Race 2 | 26.1/Technical Regulations 2.7.1 - Improper manner of assembly of diffuser | Team fine | - | \$ 500 | 228 |
| Crosslink Competition | 9 | FR | Road America | 17 May 2021 | Race 2 | FR Technical Regulations 3.7.3 - Protest against height and compliance of diffuser | Protest disallowed | - | \$ - | 220 |
| Crosslink Competition | 9 | FR | Michelin Raceway Road Atlanta | 27 March 2021 | Race 1 | 26.1/TAMFR-2021-003/Ligier Bulletin F3-11 - Spacers for ECU cooling not installed | Team fine | - | \$ 250 | 111 |
| Crosslink Competition | 14 | FR | Michelin Raceway Road Atlanta | 25 March 2021 | Pre-Event Tech | 26.1/Tech Regs 15.2.5/TAMF3-2019-006 - Halo FIA label and hologram | Team reprimand and sealing and confiscation of component | 1 | \$ - | 106 |
| Crosslink Competition | | | | | | | Total Reprimands and Fines | 2 | \$ 750 | |
| Crosslink/Kiwi Motorsport | 66 | F4 | Mid-Ohio Sports Car Course | 24 June 2021 | Pre-Event Tech | 28.2 - Second engine change during the season for any reason/28.7 - Failure to notify Technical Delegate of engine change | Rescission of Decision 314 and Team reprimand | 1 | \$ - | 315 |
| Crosslink/Kiwi Motorsport | 66 | F4 | Mid-Ohio Sports Car Course | 24 June 2021 | Pre-Event Tech | 28.2 - Second engine change during the season for any reason/28.7 - Failure to notify Technical Delegate of engine change | Team fines (rescinded by Decision 315) | - | \$ - | 314 |
| Crosslink/Kiwi Motorsport | 07 | F4 | Mid-Ohio Sports Car Course | 26 June 2021 | Race 1 | 26.9/46/CRBF4-2021-001 - Video card late or not compliant | Team fine | - | \$ 100 | 308 |
| Crosslink/Kiwi Motorsport | 66 | F4 | Mid-Ohio Sports Car Course | 26 June 2021 | Race 1 | 26.9/46/CRBF4-2021-001 - Video card late or not compliant | Team fine | - | \$ 100 | 308 |
| Crosslink/Kiwi Motorsport | 66 | F4 | Road America | 03 June 2021 | Post-Event Tech | 26.1/Technical Regulations 2.7.1 read with TAMF4-2021-002, TAMF4-2020-006 & TAMF4-2020-008 - Transmission Seals | No further action | - | \$ - | 227 |
| Crosslink/Kiwi Motorsport | 32 | F4 | Road America | 14 May 2021 | Pre-Event Tech | 26.1/Technical Regulations 2.7.1 read with TAMF4-2021-002, TAMF4-2020-006 & TAMF4-2020-008 - Transmission Seals | Sealing and confiscation of component | - | \$ - | 202 |
| Crosslink/Kiwi Motorsport | 66 | F4 | Road America | 14 May 2021 | Pre-Event Tech | 26.1/Technical Regulations 2.7.1 read with TAMF4-2021-002, TAMF4-2020-006 & TAMF4-2020-008 - Transmission Seals | Sealing and confiscation of component | - | \$ - | 201 |
| Crosslink/Kiwi Motorsport | | | | | | | Total Reprimands and Fines | 1 | \$ 200 | |
| DEForce Racing | 17 | F4 | Brainerd International Raceway | 17 July 2021 | Qualifying | 26.3(b) - Fire extinguisher not in armed position for on track session | Team reprimand | 1 | \$ - | 428 |
| DEForce Racing | | | | | | | Total Reprimands and Fines | 1 | \$ - | |
| Gonella Racing | 26 | F4 | Road America | 15 May 2021 | Qualifying | 26.3(b) - Fire extinguisher not in armed position for on track session | Team reprimand | 1 | \$ - | 208 |
| Gonella Racing | | | | | | | Total Reprimands and Fines | 1 | \$ - | |

Stewards Decisions - Teams
2021 F4 United States and FR Americas Championships



| Competitor | Car # | Class | Circuit | Session Date | Session | Article # / Offense: | Decision | Rep | Fine | Dec. # |
|-------------------------------|-------|-------|--------------------------------|---------------|-----------------|---|--|-----|----------|--------|
| Jay Howard Driver Development | 5 | F4 | Road America | 17 May 2021 | Race 3 | 24.3 - Non-compliant qualifying or race tires | Three grid places and team fine | - | \$ 250 | 221 |
| Jay Howard Driver Development | 7 | F4 | Road America | 16 May 2021 | Race 2 | 26.3(b) - Fire extinguisher not in armed position for on track session | Team reprimand | 1 | \$ - | 218 |
| Jay Howard Driver Development | 7 | F4 | Road America | 16 May 2021 | Race 2 | F4 Technical Regulations 3.14.1.d, 3.14.1.g & 3.14.3 - Non-compliant skid block - thickness less than minimum allowed | Ten grid places and team fine | - | \$ 750 | 217 |
| Jay Howard Driver Development | 6 | F4 | Road America | 15 May 2021 | Qualifying | 26.3(b) - Fire extinguisher not in armed position for on track session | Team reprimand | 1 | \$ - | 209 |
| Jay Howard Driver Development | 7 | FR | Michelin Raceway Road Atlanta | 26 March 2021 | Qualifying | 26.1/Technical Regulations 2.7.1/TAMFR-2020-027/TAMFR-2021-003 - Configuration of spacers for front wing main plane | Team fine | - | \$ 250 | 108 |
| Jay Howard Driver Development | 7 | FR | Michelin Raceway Road Atlanta | 26 March 2021 | Qualifying | 26.3(b) - Fire extinguisher not in armed position for on track session | Team reprimand | 1 | \$ - | 107 |
| Jay Howard Driver Development | | | | | | | Total Reprimands and Fines | 3 | \$ 1,250 | |
| Momentum Motorsports | 74 | F4 | Brainerd International Raceway | 18 July 2021 | Race 3 | 26.3(k) - Engine oil below minimum level | Move to last place in the classification and team reprimand | 1 | \$ - | 425 |
| Momentum Motorsports | | | | | | | Total Reprimands and Fines | 1 | \$ - | |
| Newman Wachs Racing | 48 | FR | Brainerd International Raceway | 17 July 2021 | Race 1 | 26.3(b) - Fire extinguisher not in armed position for on track session | Team reprimand | 1 | \$ - | 430 |
| Newman Wachs Racing | 48 | FR | Mid-Ohio Sports Car Course | 27 June 2021 | Race 3 | 26.9/46/CRBF4-2021-001 - Video card late or not compliant | Team fine | - | \$ 100 | 312 |
| Newman Wachs Racing | 48 | FR | Michelin Raceway Road Atlanta | 27 March 2021 | Race 1 | 26.3(i)/TAMFR-2021-003/Ligier Bulletin F3-11 - Use of tape over gap for cooling airflow to ECU not permitted | Team fine | - | \$ 250 | 110 |
| Newman Wachs Racing | | | | | | | Total Reprimands and Fines | 1 | \$ 350 | |
| TJ Speed Motorsports | 21 | FR | Road America | 16 May 2021 | Race 1 | 26.1 - Protest against compliance of wheel bearings | Protest disallowed | - | \$ - | 226 |
| TJ Speed Motorsports | | | | | | | Total Reprimands and Fines | - | \$ - | |
| TR Racing | 32 | F4 | Road America | 04 June 2021 | Post-Event Tech | 26.1/Technical Regulations 2.7.1 read with TAMF4-2021-002, TAMF4-2020-006 & TAMF4-2020-008 - Transmission Seals | No further action | - | \$ - | 229 |
| TR Racing | | | | | | | Total Reprimands and Fines | - | \$ - | |
| Velocity Racing Development | 11 | FR | Michelin Raceway Road Atlanta | 28 March 2021 | Race 3 | 22.14 - More than three crew members over the wall for a pit stop | Team reprimand | 1 | \$ - | 120 |
| Velocity Racing Development | 11 | F4 | Michelin Raceway Road Atlanta | 28 March 2021 | Race 3 | 30.18 - Car failed to start race on wet weather tires as mandated by Race Director | 10 sec stop-and-go converted to 40 sec time penalty and team reprimand | 1 | \$ - | 116 |
| Velocity Racing Development | 27 | FR | Michelin Raceway Road Atlanta | 25 March 2021 | Pre-Event Tech | 26.1/Tech Regs 15.2.5/TAMF3-2019-006 - Halo FIA label and hologram | Team reprimand and sealing and confiscation of component | 1 | \$ - | 105 |
| Velocity Racing Development | | | | | | | Total Reprimands and Fines | 3 | \$ - | |