

F4 Technical Advisory Memo

№: TAMF4-2020-016

Date: June 12, 2020

Subject: HPD Bulletin F4-2020-EN003-00 Oil Pump Recall

HPD has found that oil pumps from a specific batch have a defect that could result in loss of oil pump failure.

See the attached HPD bulletin for details.

















