

**STEWARDS DECISION****EVENT LOCATION:****DATE:**

Circuit of the Americas

23 - 25 October 2020

**Car #**

28

**Driver**

Will Edwards

**Team**

Alliance Racing

**From:** The Stewards**Time of Incident:** 13:30**To:** The Competitor's Representative, Car No: 28**Session:**☐ Practice 1☐ Qualifying☐ Race 2**Decision No:** 607☐ Pre-Event☐ Practice 2☒ Race 1☐ Race 3**Date:** 24 October 2020**Time:** 15:10**Championship:** ☒ F4 U.S. ☐ FR Americas

The Stewards, having received ☒ a report from the Technical Delegate (document No. F4-2020-06-03) or ☐ a Protest from the Driver/Competitor of Car # [ ] , have considered the following matter and determine the following:

**Car No:** 28**Driver:** Will Edwards**Competitor:**

Alliance Racing

**Facts:**

- ☐ Use of non-compliant tire(s) during: ☐ practice ☐ qualifying or races  
☐ Weight of the car is less than the minimum specified in Article 25.1 or 25.2  
☐ Damaged, missing or incorrect seals: ☐ engine ☐ transmission ☐ shocks  
☐ Fire extinguisher not armed  
☐ Oil level is below minimum allowed in: ☐ engine ☐ transmission  
☐ Use of non-compliant oil in: ☐ engine ☐ transmission  
☐ Change of: ☐ chassis without approval ☐ engine for any reason  
☐ Failure to inform Technical Delegate of: ☐ chassis change ☐ engine change  
☐ Use of non-compliant fuel  
☐ Overall width of the car exceeds the maximum allowed

**Article:**

24.5 or 24.3  
25.5  
26.1/Tech Regs 2.7.1/TAMF4&FR-2020-008  
26.3(b)  
F4 26.3(k) or 26.3(m)/FR 26.3(e)  
26.8  
27.1 or 28.2  
27.1 or 28.7  
29.1  
F4 Tech Regs 3.3/FR Tech Regs 3.2.2

- ☒ Other: Car 28 was missing its rear tow hook on pre-grid for qualifying, and the team was told to reinstall it prior to the race. The tow hook was still missing at pre-grid prior to the race and in post-race impound/Article 26.1/Article 15.5.1(j)

**Decision:**

- ☒ Team reprimand  
☐ A drop of [ ] grid positions at the driver's next [ ] race(s)  
☐ Starting from the pit lane at the driver's next [ ] race(s)  
☐ Deleting one or more lap times: ☐ fastest lap time in session ☐ all lap times in session  
☐ Starting from the back of the qualifying grid  
☐ Driver and car will not have lap times recorded and will be reported as Did Not Finish for the entire Event  
☐ Disqualification  
☒ Monetary team fine of \$250 U.S. Dollars  
☐ A drop of [ ] places in the classification  
☐ Other:

Car 28 was missing its rear tow hook despite being told by the Chief Scrutineer to reinstall it prior to the race.

**Reason:**

**Evidence:** ☐ Video ☐ Pit Lane Report ☒ Judge of Fact Report ☐ Timing Sheet ☐ Incident Report ☐ Competitor Hearing

The Competitor is reminded of his right to appeal in accordance with Article 47 of the Sporting Regulations except where the penalties are not susceptible to appeal (Article 16.3 of the Sporting Regulations).

Brian Till  
Steward (Chairman)

Wesley Cunningham  
Steward

John Walsh  
Steward