



F4 Technical Advisory Memo

No: TAMF4-2022-006
Date: May 5, 2022
Subject: Technical Bulletin #F4-2022-EN002-00

Please see HPD Technical Bulletin regarding mandatory ECU update.