

Issue Date: 5/04/2022 Issued by: A. Salzano

## F4 ECU Update #2 Technical Bulletin # F4-2022-EN002-00



This Technical Bulletin provides information on an ECU update to be performed prior to the 2022 Road America event.

## Overview

HPD will perform the updates on the ECUs during the load-in and test day at Road America.

This update is to address an issue with the knock system not operating as intended, increasing the risk of engine damage in certain <u>atypical</u> running conditions (incorrect fuel). As a reminder, it is mandatory to only use the approved fuel at all times.

Teams are encouraged to bring all ECUs that were flashed with the original 2022 calibration to be updated at the event. ECUs will be updated free of charge. The current GIN file will still be valid.

If you have any questions regarding the content of this bulletin, please contact Andrew Salzano at <a href="mailto:asalzano@hra.com">asalzano@hra.com</a> or GRMS Admin at <a href="mailto:GRMSAdmin@hra.com">GRMSAdmin@hra.com</a>.

This document is confidential and is supplied on express condition that it shall not be lent, copied, or disclosed to any other person, or used for any other purpose without the written consent of Honda Performance Development.